

HARNESSES
DICKEY



November 6, 2006

11-07-06
10/031,974
Michael P. Brennan
Direct Dial: 248.641.1218
mbrennan@hdp.com

Director of the U.S. Patent and
Trademark Office
P. O. Box 1450
Alexandria, VA 22313-1450

Re: U.S. Patent No. 6,962,599
Issued: November 8, 2005
Inventors: John C. K. Hui
For: High Efficiency External Counterpulsation
Apparatus and Method for Controlling Same

Sir:


In proofreading the above identified application, the following error was noted which appears to require a Certificate of Correction:

Column 19, line 13, claim 1 (amendment dated 12/21/04, page 8, line 8, claim 35),
"distribution" should be --distributing--.

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

By 
Michael P. Brennan
Reg. No. 30,612

MPB/rc
Enclosure

Harness, Dickey & Pierce, P.L.C.
Attorneys and Counselors
P.O. Box 828
Bloomfield Hills, Michigan 48303 U.S.A.
248.641.1600 • fax 248.641.0270

FOR COURIER DELIVERY ONLY
5445 Corporate Drive, Suite 200
Troy, Michigan 48098 U.S.A.

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.

www.hdp.com

HARNES DICKY

Michael P. Brennan
Direct Dial: 248.641.1218
mbrennan@hdp.com



November 6, 2006

Director of the U.S. Patent and
Trademark Office
P. O. Box 1450
Alexandria, VA 22313-1450

Re: U.S. Patent No. 6,962,599
Issued: November 8, 2005
Inventors: John C. K. Hui
For: High Efficiency External Counterpulsation
Apparatus and Method for Controlling Same

Sir:


In proofreading the above identified application, the following error was noted which appears to require a Certificate of Correction:

Column 19, line 13, claim 1 (amendment dated 12/21/04, page 8, line 8, claim 35),
"distribution" should be --distributing--.

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

By 
Michael P. Brennan
Reg. No. 30,612

MPB/rc
Enclosure

Harness, Dickey & Pierce, P.L.C.
Attorneys and Counselors
P.O. Box 828
Bloomfield Hills, Michigan 48303 U.S.A.
248.641.1600 • fax 248.641.0270

FOR COURIER DELIVERY ONLY
5445 Corporate Drive, Suite 200
Troy, Michigan 48098 U.S.A.

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.

www.hdp.com

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,962,599

DATED : November 8, 2005

INVENTOR(S) : John C. K. Jui

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 19.

Line 13, claim 1, distribution" should be --distributing--.

MAILING ADDRESS OF SENDER: Michael P. Brennan, Esq.
Harness, Dickey & Pierce, PLC
P. O. Box 828
Bloomfield Hills, MI 48303

PATENT NO. 6,962,599

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO : 6,962,599

DATED : November 8, 2005

INVENTOR(S) : John C. K. Jui

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

Column 19,

Line 13, claim 1, distribution" should be --distributing--.

MAILING ADDRESS OF SENDER: Michael P. Brennan, Esq.
Harness, Dickey & Pierce, PLC
P. O. Box 828
Bloomfield Hills, MI 48303

PATENT NO. 6,962,599

No. of additional copies



Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

HARNESS
DICKEY

Michael P. Brennan
Direct Dial: 248.641.1218
mbrennan@hdp.com



November 6, 2006

Director of the U.S. Patent and
Trademark Office
P. O. Box 1450
Alexandria, VA 22313-1450

Re: Patent No. 6,962,599
Issued: November 8, 2005
Inventor(s): John C. K. Hui
For: High Efficiency External Counterpulsation
Apparatus and Method for Controlling Same

Sir:

We have noted in proofreading Patent No. 6,962,599 the following errors:

Column 1, line 66 (application page 3, line 1), "pulse finger" should be -pulse wave--.

Column 2, line 54 (application page 4, line 18), after "compressed" insert -fluid--.

Column 5, line 45 (application page 11, line 1), after "speed" delete "of".

Column 8, line 54 (application page 17, line 12), after both occurrences of "signals" delete ",".

Column 11, line 2 (application page 22, line 5), after "Immediately," insert -in--.

Column 11, line 43 (application page 23, line 11), "a" should be -an--.

Column 15, line 36 (application page 31, line 12), "(40)" should be -(400)--.

Harness, Dickey & Pierce, P.L.C.
Attorneys and Counselors
P.O. Box 828
Bloomfield Hills, Michigan 48303 U.S.A.
248.641.1600 • fax 248.641.0270

FOR COURIER DELIVERY ONLY
5445 Corporate Drive, Suite 200
Troy, Michigan 48098 U.S.A.

Metropolitan
Detroit, MI St. Louis, MO Washington, D.C.


www.hdp.com

Director of the U.S. Patent and
Trademark Office
November 6, 2006
Page 2 of 2

Column 15, line 63 (application page 32, line 10), "vale" should be --value--.


Kindly make these errors of record in your files.

Very truly yours,

A handwritten signature in black ink, appearing to read "Michael P. Brennan", with a long horizontal flourish extending to the right.

Michael P. Brennan
Reg. No. 30,612

MPB/rc



Patent No. 6,962,599

Attorney Docket No. 4857-0000017/CPF

Express Mail Label No. EV 757 778 281 US (11/6/2006)

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as express mail in an envelope addressed to:

Director of the United States Patent and Trademark Office
P.O. Box 1450
Alexandria, VA 22313-1450

on November 6, 2006.

Date

Signature

Michael P. Brennan

Typed or printed name of person signing Certificate

Note: Each paper must have its own certificate of mailing, or this certificate must identify each submitted paper.

Submitted herewith is (are):

Certificate of Correction Transmittal (in duplicate)
Certificate of Correction Form PTO/SB/44 (in duplicate)
Errors of Record Letter
Return Postcard

EV 757 778 281 US